




1. SUPPORT LABEL = PS NUMBER AND TYPE CODE (e.g. 012 SG-1 = PS-012). LOADS, TOP-OF-SUPPORT ELEVATIONS AND FOUNDATIONS: MEC-CAL-005.
2. LINE NUMBERS PER MEC-LST-001; VALVE TAGS PER MEC-LST-003 AND THE P&IDs PRO-DWG-101 TO -110.
3. SK-110 AND FG-101 INTERNAL PIPING AND SUPPORTS BY SKID VENDOR (SEE PIP-DWG-002 FOR SK-110 ARRANGEMENT).
4. INSTRUMENT, VENT AND DRAIN CONNECTIONS NOT ALL SHOWN; SEE ISOMETRICS PIP-DWG-010 TO -015.
5. 1051 / 1052 FUEL GAS AND 1042 OUTLET LATERAL ARE BURIED (DASHED); DETAILS PIP-DWG-007. PIPE-TO-SUPPORT ISOLATION PADS AT ALL SUPPORTS.